

## Improvements

- Implemented CAN bus lockup detection logic as well as CAN bus recovery logic, allowing the control panel to detect an issue and then quickly resume normal operations after the recovery.
- Implemented temporarily disabling of network monitoring while command and data channel are in operation.

## Fixes

- Updated the CAN bus kernel and ensured it is backwards compatible with existing ACS6000 boards in the field.