

Brivo Onair 11.34**11/29/2018**

This release of Brivo Onair adds new functionality to Elevators and makes improvements to Mercury manufacturing client as well as addressing other system improvements and bug fixes.

New Features

- Brivo Onair Pass can now be used with elevators. A Bluetooth Reader ID field has been added to the New Elevator page in Brivo Onair for elevators connected to ACS6000 or ACS300 panels with firmware version 5.2.8 or later.

Improvements

- Updated the Mercury panel manufacturing client to simplify the manufacturing process.
- Implemented a minor security improvement.

Fixes

- Fixed an issue where newly added holidays were not being properly recognized by control panels.
- Fixed an issue with administrator creation.

Brivo Onair 11.33**11/06/2018**

This release of Brivo Onair makes major changes to the User Interface by removing the “New” page tabs (such as Users, Groups, Sites, Schedules, and Holidays) in the Onair dropdown menus, instead directing administrators to the corresponding List pages to use the “New” buttons. Additional updates to the UI include removing the word “directory” from most list pages and standardizing page headers to use List instead of Directory. This release also addressed other system improvements and bug fixes.

Improvements

- Major change to the Brivo Onair user interface with the removal of the “New” page tabs from the Onair dropdown menus. Administrators are now instead directed to the corresponding List pages to use the “New” buttons. None of the functionality has been changed.
- Removed the word “directory” from menu labels such as Site Directory, Schedule Directory, etc. These menu labels now show Sites, Schedules, Holidays, etc.
- Standardized page headers across the application to display List instead of Directory (i.e., User List, Group List).
- Account Settings dropdown menu options are no longer visible to Assistant Administrators.

Fixes

- Fixed an issue where Live Video was not visible if the browser was not set to 100%.
- Fixed an issue where Brivo Onair events were disappearing from the activity log after a browser refresh.
- Fixed an issue where Edit and Add message were missing for some cameras.
- Fixed an issue where some components of the real time activity functionality were not loading properly.

Brivo Onair 11.32

10/17/2018

This release of Brivo Onair adds new functionality to the User Identity tab makes improvements to the look of the User Page as well as addressing other system improvements and bug fixes.

New Features

- Improvements to the User Identity tab in Brivo Onair now allow administrators to associate phone numbers and emails with a user identity in Brivo Onair rather than having to create custom fields for those entries.

Improvements

- Users can no longer register an ACS4000 panel. For more information on the ACS4000 End of Life, please visit <https://www.brivo.com/partner-resources/>

Fixes

- Fixed an issue where users who mistakenly entered a blank value when provisioning a Brivo Onair Pass would notice that the send button was then disabled. The send button is now active and ready once you have entered in an email address.
- When associating a new ACS6000 panel, reader port 1 is now defaulted to OSDP. This will allow smoother installation when installing a Wiegand or OSDP reader.
- Fixed an issue where some users were seeing an error when cancelling a Brivo Onair Pass in a pending state. The Brivo Onair Pass invitation now is cancelled as needed.
- Fixed an issue where an administrator clicking on a site name within the activity log would see the site address displayed incorrectly.
- Fixed an issue where a blank screen would appear when clicking to pop out the live view video player.

Brivo Onair 11.31

10/09/2018

This release of Brivo Onair makes improvements to the look of the User Page as well as addressing other system improvements and bug fixes.

Improvements

- This release updates the look of the Identity tab on the User Page.
- Brivo Onair's video player can now be used to view live video in Chrome, Firefox, Edge, and Safari when Adobe Flash is disabled or not installed. Flash is still required to view live video in Internet Explorer.

Fixes

- Fixes multiple display issues when viewing exacqVision recordings in Brivo Onair.
 - Camera name, date, and time will now display on recorded clips (if configured in exacqVision).
 - A split second of live feed will no longer be visible before playing a recorded clip.